


Safe screw insertion



The areas for safe screw insertion can easily be identified by picturing the ASIS and a perpendicular line on the acetabulum.